
From: Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]
Sent: 11/25/2015 2:31:01 PM
To: Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]; Amelia H Boschen (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Amelia2]
CC: Doug Wight (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Dougl7]; Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeff136]
Subject: Possum Point D, blanket and toe drain details
Attachments: Toe Drain Section View.pdf; Toe Drain Manhole.pdf; Toe Drain Plan View.pdf

Ken and Amelia,

Attached are some marked up drawings that should help illustrate the location and details of the blanket and toe drain at Possum Point D Pond Dam. I have shown the approximate limit of the clay liner, slurry wall, outfall S107 and the storm drain drop-inlet that contributes to outfall S107.

Let me know if you have any questions or need further details.

Happy Thanksgiving.

Mike W